

Time Stamp	Ignition Advance	RPM	AFM (V)	DME Voltage (V)	IAT (F)	ECT (F)	Throttle Switch	ICV (%)	Fly. Mark (Errors)	Fly. RPM (Errors)	Fly. Tooth (Count)	Flywheel Vehicle	NBO2 (V)	NBO2 Digital	FQS	BAP (PSI)	MAP (PSI)	WBO2 (AFR)	WBO2 (Lamda)	Ign. Dwell (ms)	Inj. Pulse (ms)	Fuel Pump	DME Program	AC Comp.	Codeing Plug	AuxInpu t
03:19:26:590484	10.9	906	0.83	13.41	104	196	Idle	93.3	0	2	132	944 Turbo	0.16	Lean	1	14.6	-7.62	14.99	1.02	4.9	2.3	ON	28 Pin	OFF	Removed	Disabled
03:24:19:293656	10.9	907	0.82	13.51	94	193	Idle	93.3	0	2	132	944 Turbo	0.62	Rich	1	14.6	-7.62	14.83	1.01	4.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:13:09:809284	8.18	908	0.82	13.45	100	198	Idle	93.3	0	2	132	944 Turbo	0.13	Lean	1	14.6	-7.69	14.96	1.02	4.8	2.2	ON	28 Pin	OFF	Removed	Disabled
03:30:34:184246	5.45	930	0.83	13.38	102	200	Idle	93.3	0	2	132	944 Turbo	0.76	Rich	1	14.6	-7.81	15.05	1.03	4.8	2.1	ON	28 Pin	OFF	Removed	Disabled
03:27:31:293610	10.9	969	0.9	13.42	97	193	Idle	89.4	0	2	132	944 Turbo	0.07	Lean	1	14.6	-7.62	16.66	1.13	4.7	2.2	ON	28 Pin	OFF	Removed	Disabled
03:16:04:856111	24.54	1109	1.81	13.35	107	195	Off Idle	86.2	0	2	132	944 Turbo	0.85	Rich	1	14.6	-2.24	12.66	0.86	4.7	4.3	ON	28 Pin	OFF	Removed	Disabled
03:11:50:902986	24.54	1124	1.88	13.41	97	197	Off Idle	86.3	0	2	132	944 Turbo	0.84	Rich	1	14.6	-2.23	12.58	0.86	4.6	4.7	ON	28 Pin	OFF	Removed	Disabled
03:17:18:371735	13.63	1130	1.02	13.36	105	195	Idle	83.2	0	2	132	944 Turbo	0.03	Lean	1	14.6	-8.23	20.22	1.38	4.6	2.1	ON	28 Pin	OFF	Removed	Disabled
03:17:18:293609	13.63	1133	1.02	13.36	105	195	Idle	79.4	0	2	132	944 Turbo	0.02	Lean	1	14.6	-8.21	20.23	1.38	4.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:29:34:027989	24.54	1521	1.97	13.39	100	197	Off Idle	86.9	0	2	132	944 Turbo	0.86	Rich	1	14.7	-2.23	12.6	0.86	4	3.8	ON	28 Pin	OFF	Removed	Disabled
03:10:59:809238	35.45	2346	1.32	13.62	96	195	Idle	70.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.5	15.02	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:10:59:824870	35.45	2347	1.3	13.61	96	195	Idle	68.4	0	2	132	944 Turbo	0.74	Rich	1	14.6	-10.5	15.02	1.02	3.5	1.3	ON	28 Pin	OFF	Removed	Disabled
03:26:30:809239	35.45	2391	1.33	13.43	96	195	Off Idle	72.5	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	16.79	1.14	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:621739	35.45	2407	1.34	13.42	96	195	Off Idle	72.1	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	18.58	1.27	3.6	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:606113	35.45	2418	1.34	13.42	96	195	Off Idle	72.3	0	2	132	944 Turbo	0.06	Lean	1	14.6	-10.48	18.96	1.29	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:26:30:918615	35.45	2418	1.33	13.45	96	195	Off Idle	72.6	0	2	132	944 Turbo	0.07	Lean	1	14.6	-10.49	16.28	1.11	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:20:46:309294	35.45	2446	1.39	13.44	100	195	Idle	68.3	0	2	132	944 Turbo	0.68	Rich	1	14.6	-10.48	15.01	1.02	3.6	1.4	ON	28 Pin	OFF	Removed	Disabled
03:26:45:606117	29.99	2449	2.81	13.42	96	195	Off Idle	70.8	0	2	132	944 Turbo	0.43	Rich	1	14.7	0	15.09	1.03	3.5	4.6	ON	28 Pin	OFF	Removed	Disabled
03:08:02:231113	13.63	2489	1.85	13.5	114	196	Off Idle	34.7	0	2	132	944 Turbo	0.06	Lean	1	14.6	-8.21	20.23	1.38	3.6	1.9	ON	28 Pin	OFF	Removed	Disabled
03:08:25:621738	29.99	2627	2.87	13.52	113	196	Off Idle	61.7	0	2	132	944 Turbo	0.18	Lean	1	14.6	0.01	15.1	1.03	3.4	4.9	ON	28 Pin	OFF	Removed	Disabled
03:09:07:668630	29.99	2982	3.18	13.52	108	192	Off Idle	41.5	0	2	132	944 Turbo	0.47	Lean	1	14.6	1.91	14.83	1.01	3.5	5.6	ON	28 Pin	OFF	Removed	Disabled
03:27:13:027987	36.81	3006	2.01	13.43	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.42	Lean	1	14.7	-8.4	14.88	1.01	3.5	2.1	ON	28 Pin	OFF	Removed	Disabled
03:28:36:981182	36.81	3012	2.01	13.45	99	195	Off Idle	41.3	0	2	132	944 Turbo	0.37	Lean	1	14.6	-8.4	14.97	1.02	3.5	2.2	ON	28 Pin	OFF	Removed	Disabled
03:28:36:309234	36.81	3016	2.02	13.45	99	195	Off Idle	41.4	0	2	132	944 Turbo	0.4	Lean	1	14.7	-8.4	15.02	1.02	3.6	2.2	ON	28 Pin	OFF	Removed	Disabled
03:22:29:918612	29.99	3133	3.24	13.56	96	194	Off Idle	41.5	0	2	132	944 Turbo	0.84	Rich	1	14.6	1.91	13.05	0.89	3.5	6.3	ON	28 Pin	OFF	Removed	Disabled
03:17:55:121738	36.81	3592	2.41	13.38	107	196	Off Idle	41.4	0	2	132	944 Turbo	0.53	Lean	1	14.6	-7.3	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:17:54:809239	36.81	3594	2.41	13.42	107	196	Off Idle	41.5	0	2	132	944 Turbo	0.28	Lean	1	14.6	-7.27	14.96	1.02	3.6	2.5	ON	28 Pin	OFF	Removed	Disabled
03:08:01:512361	36.81	3739	2.72	13.52	114	196	Idle	41.6	0	2	132	944 Turbo	0.64	Rich	1	14.6	-7.27	15.01	1.02	3.5	1.5	ON	28 Pin	OFF	Removed	Disabled
03:10:06:668615	20.45	3941	4.33	13.57	100	189	Off Idle	41.6	0	2	132	944 Turbo	0.9	Rich	1	14.7	16.93	10.21	0.7	3.5	15.1	ON	28 Pin	OFF	Removed	Disabled
03:10:12:309240	36.81	4173	3.08	13.5	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.82	Rich	1	14.6	-3.5	13.21	0.9	3.5	3.3	ON	28 Pin	OFF	Removed	Disabled
03:10:12:293658	36.81	4180	3.11	13.49	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-3.24	13.14	0.9	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:12:277990	36.81	4198	3.14	13.5	98	189	Off Idle	41.6	0	2	132	944 Turbo	0.83	Rich	1	14.6	-2.97	13.07	0.89	3.5	3.4	ON	28 Pin	OFF	Removed	Disabled
03:10:07:121738	20.45	4344	4.43	13.57	99	189	Off Idle	41.6	0	2	132	944 Turbo	0.91	Rich	1	14.6	17.59	11.35	0.77	3.4	15.1	ON	28 Pin	OFF	Removed	Disabled